

Tele : 2458171

BY HAND

Garrison Engineer (AF) B/R
Military Engineer Services
Chakeri, Kanpur-08


2002/Complain-I/282/E2

21 May 2024

Air Force School
Chakeri, Kanpur

VISUAL INSPECTION OF AIR FORCE SCHOOL BLDGS

1. During visual inspection of the AF School bldgs the fwg points have been observed:-
 - (a) Bldgs inspected - Admin block, Double story bldg, Lab bldg, Primary Wing and NPH / ATL bldg.
 - (b) Nature of bldgs - Permanent.
 - (c) Ceiling plaster and concrete of chajja's found cracked at certain places and rusted reinforcement are visible reqd to repair in the Admin block.
 - (d) Chajjas and ceiling needs to repair at certain places, reinforcement are visible in the Double story block.
2. All bldgs stated above found structurally sound as per visual inspection of the bldgs. Normal repairing work as stated above required in the Admin block and Double story bldg.



(Deepak Badoni)
Lt Col
Garrison Engineer (AF) B/R

Copy to:-

AGE B/R-I, Chakeri - for info
Kanpur-08

015 - put to CD
for further discussion.
Rust
21-5-24